

# Foundation Design Entry

## HOT KEY LISTS

Key	Project Manager	Schematic Editor	Simulator	HDL Editor	State Editor	Symbol Editor
+	Expand 1 level					
*	Expand Branch					
-	Collapse Branch					
Alt+Bksp						Undo
Alt+F3				Find...	Find String	
Alt+X		Exit				
Ctrl++		Zoom In			Zoom In	Zoom In
Ctrl+*	Expand All					
Ctrl+-		Zoom Out			Zoom Out	Zoom Out
Ctrl+A		Undo		Redo	Redo	
Ctrl+B		Table Setup				
Ctrl+C	Copy Project	Copy		Copy	Copy	Copy
Ctrl+D	Delete Project			Delete End		
Ctrl+E		Symbol Editor				
Ctrl+F2		Integrity Test		Toggle Bookmark		
Ctrl+G		Snap to Grid		Go to...		
Ctrl+H		Hierarchy Push			HDL Code Gen.	
Ctrl+I	Document Info.	Hierarchy Pop				
Ctrl+K		Annotate				
Ctrl+L	List of Libraries	Rotate Symbol				
Ctrl+M		Mirror Symbol				
Ctrl+N	New Project	New Sheet		New	New	New
Ctrl+O	Open Project	Open		Open	Open	Open...
Ctrl+P		Print		Print...	Print...	Print
Ctrl+S		Scratchpad		Save	Save	Save
Ctrl+T	Project Type	Printer Setup				Test Symbol
Ctrl+U		Deselect All				
Ctrl+V		Paste		Paste	Paste	Paste
Ctrl+W		Redraw Wires				
Ctrl+X		Cut		Cut	Cut	Cut
Ctrl+Y				Cut Line		
Ctrl+Z		Redo		Undo	Undo	
Del	Remove Doc.	Delete		Delete	Delete	Delete
Enter	Open Document					
F1	Help	Help	Help	Help	Help	Help
F2		Select & Drag	Cascade	Next Bookmark		
F3		Symbols	Tile	Find Next	Find Next	
F4		Draw Wires		Next Error	Next Error	
F5		Draw Buses				
F6		Draw Bus Taps				
F7		Query				
F8		Test Points	Short Step			
F9		Center	Long Step			
F10		Redraw			Redraw	Redraw
Pgdn		Full Page			Page	
PgUp		Previous Zoom			Previous	